

FIG. 1








FIG. 2





34

FIG. 5




FIG. 9A




FIG. 9B



Figure 1 is a perspective view of a vehicle interior. It shows a seat assembly 112 with a backrest 112a and a seat cushion 112b. A headrest 144 is shown in a retracted position, and a headrest 144 is shown in an extended position.

FIG. 8




FIG. 9




FIG. 9C




FIG. 14A




FIG. 10




FIG. 11






FIG. 12




FIG. 14







FIG. 13








FIG. 19




FIG. 20




FIG. 21





Figure 23

Variable	Mean	SD	Min	Max
Age	37.2	12.5	18	65
Gender	50% Male			
Marital Status	65% Married			
Education	12.5 years	2.5	8	16
Income	\$35,000	\$15,000	\$10,000	\$70,000
Health Status	75% Good			
Exercise Frequency	3 times/week	1-5	1	5
Diet Quality	70%			
Stress Level	60%			
Sleep Quality	75%			
Work Satisfaction	65%			
Family Support	80%			
Community Involvement	55%			
Life Satisfaction	70%			
Overall Well-being	75%			



**Figure 24**

1300





Figure 25



1400

**Figure 26**




Figure 27




Figure 28

1600'





Figure 29



**Figure 30**





Figure 31



**Figure 32**





Figure 33





1000

Figure 34





Figure 35

3600



**Figure 36**

3700




Figure 37

3800




Figure 38

3900




Figure 39

4000




Figure 40

4100




Figure 41



4200




Figure 42

